

# MONUMENT RECORD

Corner I.D. #


E-11

STATE OF INDIANA - COUNTY OF MONROE

Section Eighteen (18) , Township 9 North , Range 1 East

Monument Description & Remarks: Found 5/8" Rebar w/yellow plastic cap at  
East 1/4 corner of section. Rebar was flush w/ground and firmly in place.  
Plastic cap reads "Ind Gas Bauer • R.L.S. #S0457".

Recovery Tie Drawing



State of Indiana

County of Monroe

Space  
Reserved For  
Recording  
Officer

I, Michael W. Friley, County Surveyor *M.W.F.*, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; and the above data is given under my hand and seal this 29th day of January, 1996 A.D.

Indiana Registered Land Surveyor No. \_\_\_\_\_ or

Monroe County Surveyor's Office  
United States Government Agency

Monroe County Surveyor  
Title

Field Book:

96-01

Page:

7

ALAN McCLAIN  
DM. FRILEY

SEC-7, 9N, 15E  
1-17-96 52° F  
PT. SUMMIT

2" x 3"

FIND SANDSTONE STONE  
AT E. 1/4 COR.  
checked rec. list 11.86"  
N. & S. For Ind. Treaty  
N. EVIDENCE FND N. & S.  
BUT FNC. FROM STONE  
going South, East, S.W. & S.E.  
IND Treaty should be  
Approx N 50-52° W from  
previous survey stone  
checks in 1/4 section  
SECTION AS 1/4 COR.  
I SUSPECT STONE DISTANCE  
AS TREATY MONUMENT  
WHICH EXPLAINS N 44° W  
FNC.

SEE TIES

NEXT PAGE (3)

1-17-96  
P.R. @ BASE  
E. SIDE 8"  
SASSAFRASS

E. 1/4 COR (2)  
SEC-7, 9N, 15E

STONE IS SOLID  
IN GRND. 0.3' x  
0.8' x 0.7'  
OUT OF GRND.

